

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




FIGURE 1

200




FIG. 2




FIG. 3A






Fig. 3B



4
400

Fig 4



5
500

Fig 5





Fig. 6

704
703



702

Fig. 7




Fig - 8

802




Fig 9

900




Fig. 10




Fig. 11




Fig. 12




Fig. 13

Cup and Liner Selection

40	42	44	46	48	50	52	54
56	58	60	62	64	66	68	70


MH Rad 3-Hole	Univ MultiHole	Other
------------------	-------------------	-------

MaxROM	10°	5mm
--------	-----	-----

close

1480

Fig. 1014



L1500

Fig. 15





Fig. 16



L1700

Fig. 17